


# Mechanics' Temperature Quick Conversion Chart



200°F

100°C

100°C


↑ °C (Celsius)


→ °F (Fahrenheit)

200°F

$$^{\circ}\text{F} = (^{\circ}\text{C} \times 1.8) + 32$$

$$^{\circ}\text{C} = (^{\circ}\text{F} - 32) \times 0.56$$



 Chart by Yoshifumi Honda on a '81 Corvette